## MARYLAND HISTORICAL TRUST

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1	NAME	×	*			*
	HISTORIC 1533	Myrtle Avenue			MIHPN	o. B-5196
	AND/OR COMMON					
	LOCATION					
1						
	STREET & NUMBER	1500 Block Myrtle	Avenue			
	CITY, TOWN		VICINITY OF	C	ONGRESSIONAL DISTR	ICT
•	STATE		VICINITY OF	C	COUNTY	
j	CLASSIFICA	ATION				#XI
	CATEGORY	OWNERSHIP	STATUS		PRES	ENT USE
	_DISTRICT	PUBLIC	_OCCUPIED		_AGRICULTURE	_MUSEUM
	_BUILDING(S)	PRIVATE	UNOCCUPIED		_COMMERCIAL	PARK
	_STRUCTURE	ВОТН	_WORK IN PROGRESS		EDUCATIONAL	PRIVATE RESIDENCE
	SITE	PUBLIC ACQUISITION	ACCESSIBLE		_ENTERTAINMENT	_RELIGIOUS
	OBJECT	_IN PROCESS	_YES: RESTRICTED		GOVERNMENT	_SCIENTIFIC
		_BEING CONSIDERED	_YES: UNRESTRICTED		_INDUSTRIAL	_TRANSPORTATION
	2 × ×	الم المحملة الموادية الم	_NO	140.06	_MILITARY	_OTHER
NAME STREET & NUMBER			Telephone #:			
		=	in the second se			
	CITY, TOWN		VICINITY OF		STATE , Z	ip code
į	LOCATION	OF LEGAL DESCR	IPTION	Libe		
	COURTHOUSE.		70.	Folio		
	REGISTRY OF DEEDS, ET	C.		FOIL	J # :	
	STREET & NUMBER	ords Office Room 60	)1			
-	CITY, TOWN	timore City Courtho	nise		STATE	
	- Ral	timore, Maryland 3	11202			
İ		TATION IN EXIST				
	TITLE STATE				* -	
-	DATE CIT	y of Baltimore Neig	hborhood Survey	<b>y</b>		
	197	8	FEDERAL	_STATE _	COUNTY _LOCAL	
	DEPOSITORYFOR					
		wission for Histori		ural Pi	STATE STATE	
-	Bal	timore, Maryland 2	1202			

# 7 DESCRIPTION

MIHP No.8-5196

#### CONDITION

\_EXCELLENT

\_FAIR

\_DETERIORATED

\_GOOD

\_\_RUINS

CHECK ONE

\_UNALTERED

\_ALTERED

CHECK ONE

\_ORIGINAL SITE

MOVED

DATE\_\_

### DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

The rowhouse is three stories high with building and foundation walls laid in common bond and a flat roof. The first story facade is two bays wide with the bay to the left housing a flat wood garage door and the bay to the right housing a half arched aperture, now boarded, for a window. The two elements are encased in a painted wood storefront. The second and third story facades are each punctuated by three half arched apertures. Those on the second story facade are boarded over. Presumably they were hung in the same way as those windows punctuating the third story facade, that is, with four over four lights. Both sets of windows have wood sills and decorative brick window hood. The wood cornice surmounting the building facade is embellished with extra molding and a pierced wood sill and supported by four brackets.

## 8 SIGNIFICANCE

_1900-	COMMUNICATIONS	_INDUSTRY _INVENTION	POLITICS/GOVERNMENT	_OTHER (SPECIFY)	
_1800-1899	COMMERCE	_EXPLORATION/SETTLEMENT	PHILOSOPHY	_TRANSPORTATION	
1700-1799	_ART	ENGINEERING	MUSIC	_THEATER	
_1600-1699	_ARCHITECTURE	EDUCATION	MILITARY	_SOCIAL/HUMANITARIAN	4
1500-1599	AGRICULTURE	_ECONOMICS	LITERATURE	_SCULPTURE	
_1400-1499	_ARCHEOLOGY-HISTORIC	CONSERVATION	_LAW	SCIENCE	
PREHISTORIC	_ARCHEOLOGY-PREHISTORIC	_COMMUNITY PLANNING	_LANDSCAPE ARCHITECTURE	_RELIGION	_
PERIOD	AF	REAS OF SIGNIFICANCE CH	IECK AND JUSTIFY BELOW		

STATEMENT OF SIGNIFICANCE

The 1500 block of Myrtle Avenue included houses of a variety of styles and sizes. Some were very ornately decorated, for example the window hoods of #1533. Others were simple and typical of housing in the area (#1531). The differing treatments of cornices, door and window lintels, and window sills provided a diversity along the streetscape. This block was razed c.1976.

1533 Myrtle Avenue Sanborn Map 1953, Volume 2, Sheet 186 Demolished 1976









